



The following photographs depict sites that were identified in the EnviroSite Government Records Report dated 03/21/2023. Reported Sites 6 and 8 could not be directly observed in the field due to a lack of right-of-entry permissions from the respective property owners.



Photograph 1 – View looking south at the former location of Reported Site 1, Quintanilla Tire Shop. The site is no longer active and is a private residence.



Photograph 4 – View looking southeast at oil tankers located near the entrance of Reported Site 4, Rio Farms Gas Plant. The site was inaccessible due to a lack of right-of-entry permissions.



Photograph 2 – View looking east at Reported Site 2, Tennessee Gas Company.



Photograph 5 – View looking east from the existing Raymondville Drain at Reported Site 5, North Alamo Water Supply Corporation Reverses Osmosis Wastewater Treatment Plant.



Photograph 3 – View looking south at the entrance to Reported Site 3, Key Energy Service.



Photograph 6 – View looking west at an above-ground storage tank associated with Reported Site 5.



Photograph 7 – View looking northwest at the entrance to Reported Site 7, Lower Rio Grande National Wildlife Refuge.



Photograph 8 – View looking north at an abandoned and collapsed structure at the entrance of Reported Site 9, Raymondville Historical Landfill.

[The remainder of this page is intentionally blank.]



The following photographs depict the sites that were identified during field investigations but were not listed in the Envirosite Government Records Report. Unreported Site 4, Dallas Petroleum Group Oil and Gas Facility, was not directly investigated in the field due to lack of right-of-entry permissions from the property owners.



Photograph 9 – View northwest at Unreported Site 1, discarded gas tanks located along 12th Street.




Photograph 12 – View looking southeast at construction debris located at Unreported Site 3.



Photograph 10 – View south at tank batteries located at Unreported Site 2. This photograph was taken from a publicly accessible roadway.



Photograph 13 – View looking southwest at Unreported Site 5, Energy Transfer Raymondville Facility.



Photograph 11 – View looking north at Unreported Site 3, Construction Staging Area.



Photograph 14 – View looking south at Unreported Site 6, an illegal dumping area located within the RDP study corridor.



Photograph 15 – View looking northwest at Unreported Site 7, a farming staging area. This photograph was taken from a publicly accessible roadway.

[The remainder of this page is intentionally blank.]