



Historical Aerial Photo Report | 2023

GIS Ready Format

Order Number: 84790

Report Generated: 03/27/2023

Project Name: Raymondville Drain Project

Project Number: U3408-F0001

Raymondville Drain Project
Route 186
Hidalgo, TX

Contact us at:
(866) 211-2028
envirositecorp.com

Envirosite's Historical Aerial Photo Report is designed to assist in evaluating a subject property resulting from past activities. EnviroSite's Historical Aerial Photo Report includes a search of available historical aerial photographs, dating back to the 1930s, or earliest available photographs.

ENVIROSITE SEARCHED SOURCES

SUBJECT PROPERTY:

Raymondville Drain Project
Route 186
Hidalgo, TX

<u>YEAR:</u>	<u>SCALE:</u>	<u>NUMBER OF PHOTO(S):</u>	<u>SOURCE:</u>
1955	1:71,500	12	Single Frames
1972	1:120,626	1	Single Frames
1972	1:121,622	1	Single Frames
1972	1:122,996	3	Single Frames
1980	1:80,000	6	Single Frames
1983	1:58,000	6	NHAP
1995	1:24,000	7	DOQ
1995	1:24,000	8	DOQ
1995	1:40,000	3	NAPP
2002	1:40,000	13	NAPP
2010	1:24,000	7	NAIP
2010	1:24,000	7	NAIP
2012	1:24,000	7	NAIP
2012	1:24,000	7	NAIP
2014	1:24,000	7	NAIP
2014	1:24,000	7	NAIP
2016	1:24,000	7	NAIP
2016	1:24,000	7	NAIP
2020	1:24,000	2	NAIP
2020	1:24,000	3	NAIP
2020	1:24,000	3	NAIP
2020	1:24,000	3	NAIP
2020	1:24,000	3	NAIP

Disclaimer - Copyright and Trademark Notice

All information contained in this report are based on data available from various public, government and other sources and are based upon the best data available from those sources. The information available in this report may be available from other sources and is not exclusive or the exclusive property of EnviroSite Corporation.

NO WARRANTY EXPRESSED OR IMPLIED, IS MADE IN CONNECTION WITH THIS REPORT, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. ALL RISK IS ASSUMED BY USER AND EnviroSite assumes no liability for faulty or inaccurate information. The Reports may utilize a variety of public and other sources reasonably available to EnviroSite. EnviroSite cannot, and does not assure, warrant, guarantee or assume any liability for the correctness, comprehensiveness, timeliness or completeness of any of such information, nor is the information in any Report to be construed as legal advice with respect to environmental risks associated with any property. EnviroSite shall not be liable to anyone for any claims, causes of action, suits, damages, losses, costs and expenses (including, without limitation, attorneys' fees and costs) arising out of or caused by this report regardless of the acts, errors or omissions, or negligence of EnviroSite. Any damages shall be limited to the purchase price of the report.

Purchaser of the report accepts the report "As Is". The report is intended only to provide information only and should not be considered as providing any legal advice, prediction, forecast, or fact as to the environmental risk for any specific property. Reports are proprietary to EnviroSite, and contain copyrighted material and trademarks of EnviroSite. All other trademarks used herein are the property of their respective owners. All rights of EnviroSite as to the Reports are reserved.

YEAR:

1955
1972
1972
1972
1980
1983
1995
1995
1995
2002
2010
2010
2012
2012
2014
2014
2016
2016
2020
2020
2020
2020
2020

DOWNLOAD LINK(S):

[Click here to download maps](#)
[Click here to download maps](#)
[Click here to download maps](#)
[Click here to download maps](#)
[Click here to download maps](#)
[Click here to download maps](#)
[Click here to download maps](#)
[Click here to download maps](#)
[Click here to download maps](#)
[Click here to download maps](#)
[Click here to download maps](#)
[Click here to download maps](#)
[Click here to download maps](#)
[Click here to download maps](#)
[Click here to download maps](#)
[Click here to download maps](#)
[Click here to download maps](#)
[Click here to download maps](#)
[Click here to download maps](#)
[Click here to download maps](#)
[Click here to download maps](#)